ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0481, W0500, W0469, W0467, W0510	Doddenakundi Main Rd, NA, 3rd Crs, 4th Crs	kalpatharu apartment and srinindhi badavana opp. T
Segment No.	**Total Length (m)**	
8/C-W0481/S121314	417.33	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	142.25	77.577248	13.054514	77.576623	13.053383	W0500	W0320
2	275.08	77.576178	13.055192	77.578363	13.053930	RI-S62	W0469

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Cross Roads and drain near kalpatharu apartment and srinindhi badavana opp. To tata nagar ward no 8 (Kodigehalli) Kodigehalli Sub-Div	2000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Cross Roads and drain near kalpatharu apartment and srinindhi badavana opp. To tata nagar ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-16-000010
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/333/2016-17	24/03/2016	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/03/2016	23/03/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SANJAY REDDY .H.J		0.00
Phone No.	**E-Mail ID**	

9900003978

Field Inspection Details

Number of Trees	Any Other Information	Name
6		srinivasa Murthy
Date of Inspection	**Remarks**	
13/08/2016	completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0481, W0500, W0469, W0467,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	13/08/2016	12/09/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0481, W0500, W0469, W0467,

SE	VASU K M	13/08/2016	12/09/2016	COMPLETED
EE	YARAPPA REDDY	13/08/2016	12/09/2016	COMPLETED
AEE	SHIVA KUMAR	13/08/2016	12/09/2016	COMPLETED
AE	SRINIVASA MURTHY	13/08/2016	12/09/2016	COMPLETED
AE	SRINIVASA MURTHY	13/08/2016	12/09/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0481, W0500, W0469, W0467,